

Table 1

COMMUTER PARKING LOTS
Current Use & Peak Utilization
Spring, 2009

Municipality	Location	Capacity	Current Count		
			Date	Vehicle Count	Percent Full
Branford	I-95 at Maintenance Garage (exit 56)	40	4/29	8	20%
	Route 1 at Cherry Hill	124	4/29	31	25%
	I-95 at Route 1 (exit 55)	70	4/29	37	53%
	Branford Railroad Station	205	4/29	218	106%
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	4/30	21	72%
	Route 1 at Kimberly Avenue (East Lot)	20	4/30	16	80%
Guilford	I-95 at Route 77 (exit 58 - East Lot)	20	4/30	2	10%
	I-95 at Route 1 (exit 57)	113	4/30	12	11%
	I-95 at Route 77 (exit 58 - West Lot)	45	4/30	14	31%
	I-95 at Goose Lane (exit 59)	58	4/30	6	10%
	Guilford Railroad Station	176	4/30	159	90%
Madison	I-95 at Route 79 (exit 61)	197	4/30	59	30%
	Madison Railroad Station	313	4/30	154	49%
Meriden	I-691 at Lewis Avenue	55	4/30	21	38%
	I-691 at State Street	31	4/30	1	3%
	I-91 at Bee Street	72	4/30	22	31%
Milford	I-95 at Old Gate Lane (exit 40)	75	4/30	40	53%
	I-95 at School House Road (exit 35)	46	4/30	15	33%
	Route 1 at Milford Connector	25	4/30	24	96%
	Route 15 at Wheelers Farms Road (exit 5)	59	4/30	26	44%
	Milford Railroad Station at High Street	444	4/30	443	100%
New Haven	Union Station Garage (1)	1037	4/30	1009	97%
North Haven	Route 40 at Divine Street	109	4/30	111	102%
	Route 5 at Divine Street	103	4/30	113	110%
Orange	Route 15 at Route 34 (exit 58)	154	4/30	94	61%
Wallingford	Route 5 at Wharton Brook Connector	79	4/30	29	37%
	Route 15 at Route 5 (exit 66E)	81	4/30	50	62%
	I-91 at Route 68 (exit 15)	105	4/30	39	37%
	Wallingford Railroad Station	25	4/30	7	28%
West Haven	I-95 at Route 122 (exit 43)	74	4/30	25	34%
TOTAL		3,984		2,806	70%

(1) statistics for Union Station Garage are a daily total of vehicles parked

COMMUTER PARKING LOTS

Spring, 2009 Data

Municipality	Location	Capacity	Vehicle Count - April, 2009		Five Year Comparison				
			Count	Percent Full	Apr, 2008	Apr, 2007	May, 2006	May, 2005	May, 2004
Branford	I-95 at Maintenance Garage (exit 56)	40	8	20%	7	7	7	9	7
	Route 1 at Cherry Hill	124	31	25%	32	31	25	31	15
	I-95 at Route 1 (exit 55)	70	37	53%	35	18	28	21	22
	Branford Railroad Station	205	218	106%	221	180	193	133	144
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	21	72%	19	8	13	8	11
	Route 1 at Kimberly Avenue (East Lot)	20	16	80%	14	12	11	1	10
Guilford	I-95 at Route 77 (exit 58 - East Lot)	113	2	2%	7	6	5	11	9
	I-95 at Route 77 (exit 58 - West Lot)	45	12	27%	10	24	13	Closed	29
	I-95 at Goose Lane (exit 59)	58	14	24%	15	12	18	20	3
	I-95 at Route 1 (exit 57)	20	6	30%	24	15	10	9	16
	Guilford Railroad Station	176	159	90%	154	178	126	132	133
Madison	I-95 at Route 79 (exit 61)	197	59	30%	61	23	27	26	24
	Madison Railroad Station	313	154	49%	160	131	165	137	123
Meriden	I-691 at Lewis Avenue (exit 6)	55	21	38%	27	11	17	11	3
	I-691 at State Street	31	1	3%	0	0	3	5	6
	I-91 at Bee Street	72	22	31%	22	23	23	29	12
Milford	I-95 at Old Gate Lane (exit 40) - Lot 2	75	40	53%	39	5	Closed	11	3
	I-95 at School House Road (exit 35)	46	15	33%	13	12	15	14	4
	Route 1 at Milford Connector	25	24	96%	24	20	25	10	10
	Route 15 at Wheelers Farms Road (exit 55)	59	26	44%	27	29	40	16	6
	Milford Railroad Station at High Street	444	443	100%	449	436	405	390	342
New Haven	Union Station Garage (1)	1037	1009	97%	1005	1002	1045	1125	1026
North Haven	Route 40 at Divine Street	109	111	102%	115	51	55	40	60
	Route 5 at Divine Street	103	113	110%	112	68	78	55	56
Orange	Route 15 at Route 34 (exit 58)	154	94	61%	92	71	102	76	73
Wallingford	Route 5 at Wharton Brook Connector	79	29	37%	30	52	23	28	19
	Route 15 at Route 5 (exit 66E)	81	50	62%	52	30	23	35	26
	I-91 at Route 68 (exit 15)	105	39	37%	37	60	38	8	24
	Wallingford Railroad Sta	25	7	28%	9	18	17	18	6
West Haven	I-95 at Route 122 (exit 43)	74	25	34%	30	15	26	27	11
TOTAL		3,984	2,806	70%	2,835	2,548	2,576	2,436	2,233

(1) data for Union Station supplied by New Haven Parking Authority